

Customer Name	Date In	Type of Equipment	Customer's Project Status	Statement For Customer	Delivery Req	Pick Up Req
				very low torque, not needed till early spring.		
our B&S Core	7/14/2017	Starter	Shop Backlog Awaiting Repair		<input type="checkbox"/>	<input type="checkbox"/>
our Kohler core	7/14/2017	Starter	Shop Backlog Awaiting Repair		<input type="checkbox"/>	<input type="checkbox"/>
Ray Fagnoli	12/27/2017	Engine-Gas 4 Cyc Horz Air Cooled	Shop Backlog Awaiting Repair		<input type="checkbox"/>	<input type="checkbox"/>
				assess rebuildability of 1977 cast block. Cylinder excellent, reattach head, leak down shows intake valve. Break down valve train and research options. Guides are at or just over spec but two reamers are NLA as some other parts. Leakage was cupped valve trapping carbon. Both valves are available. Valve seats look good. Option to have reamers made is expensive, otherwise go with next best fix. Options not yet discussed.		
Scott Mathewson	1/15/2018	Snow Blower	Shop Backlog Awaiting Repair		<input type="checkbox"/>	<input type="checkbox"/>
				fuel line, tire pressure, service.		
Sherrie Brennan	1/15/2018	Garden Tractor	Shop Backlog Awaiting Repair		<input type="checkbox"/>	<input type="checkbox"/>
				no start.		
shop	2/13/2017	Any Type (When Required field)	Shop Backlog Awaiting Repair		<input type="checkbox"/>	<input type="checkbox"/>
				dextronIII in bushing draws		