

WOStatusOnLineOpenWork (History - Job not Complete)

Date Received Last Name

4/25/2026 Rasid

ESA No

1380695

To Shop Commen

deck not level or hanging in air rt side.Small oil leak - find and report to Ray

Work Performed

UNITHIST.[History

4/22/2026 Meza

ESA No

2857126

To Shop Commen

will not start and install new wire head

Work Performed

need to finsih fuel delivery and spark and compresion test.

UNITHIST.[History

4/20/2026 Vaughn

ESA No

1380691

To Shop Commen

will not start

Work Performed

initial testing arrested as no spark, coil wire broke - typical of this metal clad plug connector - handle with care or it breaks.

UNITHIST.[History

4/19/2026 Nale

ESA No

2857123

To Shop Commen

using propane, 3 attempts to start fail, battery kept cranking, on last attempt popped loudly.

Work Performed

attempting to obtain an english version of wire diagram, in mean time diagnostics indicate propane not admisistered to carb-tests to conntinie.

UNITHIST.[History

Date Received Last Name

4/17/2026 Kurosky

ESA No

2857106

To Shop Comment

fixed special handle bolt by barrow from Jamie unit here

Work Performed

she to paid \$25 for a special part we barrowed and reordered for the pivot of the bagger flap pn532419945 not an inventory issue. Gave owner credit for the part we barrowed and have to order which won't be in for 10 days. No income to us,

UNITHIST.[History]

4/15/2026 Murphy

ESA No

2857107

To Shop Comment

no start, check blade,and do check list

Work Performed

no cranking has been corrected, details to follow, soon to complete-a clip broken.

UNITHIST.[History]

4/14/2026 Strauss

ESA No

2857108

To Shop Comment

did start, does not now, black smoke, blade AND engagement,minor or call.service. Hood to be discarded and bill adjusted.

Work Performed

Need work complete record posted, in mean time, lights and grill in progress and waiting for a proper switch due in saturday.

UNITHIST.[History]

4/11/2026 Stewart

ESA No

2857110

To Shop Comment

needs a battery/check charging,oil/tune/service as indicated,front tires were soft and filled.Battery found 725-17335 = 11 ah/210cc!
(Superseded to 490-280-F017

Work Performed

redesign battery to earlier battery cage and better battery, overall cheaper and better-order parts, Balance of work complete needs update.

UNITHIST.[History]

4/10/2026 Chrispell

ESA No

2857103

To Shop Comment

it is apart in box, runs wear specs andlist item tests, then hw will take and pant apart.

Work Performed

research mostly on paper, parts status review partial completed.

UNITHIST.[History]

Date Received Last Name

8/3/2025 VanDervort

ESA No

light warranty

To Shop Commen

left front headlight socket bad. Sent email.

Work Performed

contact Kubota 3 times for minor warranty, they have moved to Kirkwood. I have no feedback.

UNITHIST.[History

Athan

ESA No

28578115

To Shop Commen

Work Performed

UNITHIST.[History