

Customer Name	Date In	Type of Equipment	Customer's Project Status	Statement For Customer	Delivery Req	Pick Up Req
Kohler core			Awaiting Repair			
Robert Dollinger	3/8/2018	Inverter Power Unit	On Hold - Customer Feedback Needed		<input type="checkbox"/>	<input type="checkbox"/>
if we proceed, may exceed \$200 and will need a deposit as all special order parts. Some parts are no longer available.						
shop	2/13/2017	Any Type (When Required field)	Shop Backlog Awaiting Repair		<input type="checkbox"/>	<input type="checkbox"/>
dextronIII in bushing draws						